


Fig. 1.

A. Original Error for film;

B. after stretching by 100%.



- Fig. 2 .
- a. Original Exxon 601 film without MW radiation
 - b. Middle part No Sensitizer, after MW radiation @ 300 ft/min
3.0 kW
 - c. Middle part No Sensitizer, MW radiation @ 300 ft/min, 3.0 kW
 - d. Sensitizer ASS-1, ultrasonic spray on the Exxon film and immediately MW radiation @ 300 ft/min, 3.0 kW.




Fig 3 . Various pattern created on the paper
 after microwave irradiation with and without
 applied.




Fig 4. *Two pieces of fabric.*




Fig 5

Enlarged pattern of diamond shape